



# MULTI-RANGE TESTER

**RANGE LIMIT  
WRIST STRAP  
650K TO 14MEG OHMS**

**FOOT STRAP  
650K TO 110MEG OHMS**

**SHOE  
800K TO 1.4GIG OHMS**




**RANGE SPECIFICATIONS  
WRIST STRAP (TP1 TO JACK A WITH SWITCH ON WRIST STRAP)  
750K OHMS - 10MEG OHMS**

**FOOT STRAP (TP1 TO JACK B WITH SWITCH ON FOOT STRAP)  
750K OHMS - 35MEG OHMS**

**SHOES (TP1 TO JACK C WITH SWITCH ON SHOE) 750K OHMS - 1GIG OHMS**

**ALL RANGES, EXCEPT UPPER SHOE +/-10% TOLERANCES  
RANGES FOR UPPER SHOE +/-20%**



TEST POINT 1 (TP1)

JACK A

JACK B&C